

Copyright. All Rights Reserved.

This work is copyright and cannot be produced or copied in any form or by any means (graphic, electronic or mechanical including photocopying) without the written permission of the originator. Any license, express or implied, to use this document for any purpose whatsoever is restricted to the terms of the agreement or implied agreement between the originator and the instructing party.

Levels and contours are relative to an Ordnance Survey Datum

Figured dimensions in millimetres.

All drawings are to be read in conjunction with Architectural Specification.

SCALE BAR 1:200

Drawing to be read in conjunction with all relevant Consultants Reports that form part of the Part 8 Application.

**General Conservation Notes** A. All drawings to be read in conjunction with the Conservation Architect's current versions of Conservation Reports in 3 Volumes: Vol 1 – Conservation Report – Architectural Inventory and Appraisal

Vol 3 - Conservation Report - Architectural Heritage Impact Assessment Details to be confirmed on opening up and subject to agreement with the

Vol 2 – Preliminary Conservation Repair Recommendations

Conservation Officer / Project Conservation Architect.

All works to be carried out by suitably experienced Heritage Contractors (and Specialist Heritage Sub-Contractors) who have qualified through Suitability Assessment at Pre-Tender Stage.

## Schedule of Works

Removal of all vegetation and organic growth to rainwater goods, barges, copings, parapet, and roofs. Investigate barge capping which appears to be failing. Allow for full replacement on both sides with lime-based flaunching.

Localised repairs to slate roof to replace broken or slipped slates using natural slate to match in composition and size. Allow for partial re-bedding and clamping of parapet wall stones and new lead

cover flashing along entire length. Carefully rake out any cementitious pointing to chimneys and parapet, re-point

using lime mortar. Replace all flashings on roof complete using lead.

Localised repair of timber roof structure is anticipated - requires inspection to confirm extent of damage from water ingress.

Investigation of roofs to arrow-head bays on east elevation is required to

determine condition and repairs required. Remove all vegetation to elevations complete. (Ridges, pediments, mortar joints) Remove cement strap pointing to front and rear elevations and to chimneys and

parapet complete. Rake out open joints and repoint using lime mortar. Rake out vegetation and open joints to internal yard elevations and repoint using lime mortar – allow for 25%. Removal of tarmac surfacing abutting foot of buildings, lowering of ground level and formation of a land drain [width TBC by design team on opening up] to

building perimeter (leave trench open during works to allow foot of walls to dry). Recalculate and renew cast iron rainwater disposal system complete (Refurbish and reusing existing elements where possible and appropriate). Installation and connection of new branch drainpipes from any new downpipe locations to existing stormwater drains as required. Installation of new concrete gullies with cast iron grates to the foot of each

Remove all redundant cabling and fixings. Consolidate and tidy external cabling. Removal of external lights and Installation of Internal / External lighting to

Exhibition Designer's details & specifications
Removal of existing traffic barrier and installation of a revised vehicle access security system (automated rising bollards) at the vehicle entrance through the Gaol gatehouse archway serving the Governor's house & existing Convent access beyond (subject to detailed design & ground conditions on opening up) Refurbish and draughtproof all existing timber external doors and remove modern

Remove interior dry lining and gypsum ceiling plaster from 3 x cells on upper floor. Rake out and repoint stone using lime mortar and replaster using lime plaster and

Remove modern non-breathable paint finishes where applied to masonry or lime Brush down and light clean all exposed stone walls and ceilings, remove modern paint finishes and allow for redecoration using breathable masonry paint in ground

Brush down and light clean to cell [which retain historic decoration] to remove

flaking paint but ensure to retain the original decoration scheme. Rust treat any existing cast iron features and repaint (railings, gates, window

Remove all interior signage and install new improved/updated information boards. stage.

**Demolition Works** 

Proposed Works

23.



Comhairle Contae Thiobraid Árann **Tipperary County Council** 

REVISION SCHEDULE				
NO.	DATE	ISSUED BY	DESCRIPTION	
D4	00/44/0000	OTA!	L	
P1	28/11/2023	SIW	Issue for Part 8 Application	

NENAGH HISTORIC & CULTURAL QUARTER PART 8 APPLICATION

TIPPERARY COUNTY COUNCIL

PROJECT TEAM

19 Merrion Square, Dublin 2, Ireland Tel: +353 (0)1 669 3000 Email: mail@stwarchitects.com Web: www.stwarchitects.com

GATEHOUSE - PROPOSED WORKS (NHCQ ZONE 7)

SCALE @A1	ISSUED:	
As indicated	28/11/2023	
DRAWN BY:	CHECKED BY:	
MT	DF	
PROJECT NO.	PROJECT ARCHITECT:	
20165	DAVID FLANNERY	
DRAWING NO.		REVISION

NHQ-STW-07-ZZ-DR-A-07146

PRJ-STW-00-ZZ-M3-A-0001

P1